## AS-BUILT REPAIR QUANTITY TABLE NOTES REPAIR LOCATIONS AND ESTIMATED QUANTITIES ARE GIVEN WITH THE BEST INFORMATION AVAILABLE. IF ADDITIONAL REPAIRS NOT SHOWN ON THE DRAWINGS ARE DEEMED NECESSARY BY THE ENGINEER, THE ENGINEER WILL NOTE ON THE DRAWINGS THE APPROXIMATE LOCATIONS AND DESCRIPTION OF THE REPAIRS AND ADJUST THE ACTUAL QUANTITIES ENTERED INTO THE AS-BUILT REPAIR QUANTITY TABLE. REPAIRS BENT 2 SHOTCRETE REPAIRS CAP COLUMN FOR CAP REPAIRS, SEE "TYPICAL CAP AND COLUMN REPAIR DETAILS" SHEET. EPOXY RESIN INJECTION CAP COLUMN EPOXY COATING TOP OF BENT CAP -SPAN C FACE VALUES IN CHARTS REPRESENT ESTIMATED REPAIR TOTALS AFTER REMOVAL OF UNSOUND CONCRETE, MIN. OF 1" BEHIND REBAR AND MIN.1" CLEAR TO SAWCUT. NO REPAIRS NOTED FOR BENT 2 DURING INSPECTION BY STRUCTURES MANAGEMENT UNIT. THE CONTRACTOR AND ENGINEER SHALL INSPECT THE BENT PRIOR TO BEGINNING WORK. SPAN B FACE TOP OF CAP PROJECT NO. I-5756 <u>END</u> VIEW END VIEW SPAN B FACE SPAN C FACE NORTH FACE SOUTH FACE HAYWOOD -SPAN B FACE BRIDGE NO. SHEET 2 OF 2 John a. Yannaccon ESPAEL CARO, DEPARTMENT OF TRANSPORTATION SPAN C FACE SEAL 3 32492 UNDERSIDE OF CAP 3/21/2016 DOCUMENT NOT CONSIDERED FINAL UNLESS ALL SIGNATURES COMPLETED W.O.KEITH DATE : \_\_11/15 DRAWN BY : DATE : 12/15 CHECKED BY : J. YANNACCONE

ESTIMATE ACTUAL AREA VOLUME AREA VOLUME SF CF SF CF

LN. FT

0.0 0.0

0.0 0.0

LN. FT

0.0

0.0

DAMAGED AREA

COUNTY

SHEET NO S-108

TOTAL SHEETS 122

231

STATE OF NORTH CAROLINA

BENT 2

NO. BY:

DATE:

REVISIONS

DATE: